

## **NONCOMPLIANCE REPORT**

Attachment to Atlanta Gold Corporation's Discharge Monitoring Reports

**January 2017** – The weekly arsenic results for the effluent were 9 ug/L, 12 ug/L, 9 ug/L and 8 ug/L. The one result over the compliance limit was probably due to activity in the adit. The water treatment operator had to replace additional filter material as there was a collapse within the 900 crosscut behind the dam.

**February 2017** – With 12' of snowfall, limited access to the site and limited services to change filters, AGC could not obtain the first week's samples. In addition, these conditions resulted in a slight increase in the effluent weir samples for the month. The arsenic results were 11 ug/L, 22 ug/L and 11 ug/L.

**March 2017** – The results for arsenic for the weekly effluent sampling were 22 ug/L, 7 ug/L, 6 ug/L and 5 ug/L. On the day that the 22 ug/L sample was taken, Atlanta received 7" snow and the influent weir water spiked from 52.6 gpm the previous day to 75.4 gpm.